

Service Bulletin

Priority: **Medium**

No 8 2005-07-05

General maintenance

System Applicability: MARINFLOC EBBWCS of all types

Important:

It has been found necessary to point out how important the general maintenance is! Many problems can be avoided if attention is drawn to the regular maintenance.

Please read the chapter named "Maintenance" and "Back-flushing of filters" in the Operator's Manual. (If you don't find the manual onboard you can, and we strongly recommend you to, order one or more copy/copies from our Service Department, service@marinfloc.com).

We especially want to remind about/point out following things:

- When using CIP cleaning fluids/liquids try to avoid to get this fluid into the bilge wells, bilge tanks and sludge/waste oil tanks as far as possible! They don't only emulsify Bilge Water; they also emulsify WO/Sludge very strongly which in the end makes it difficult to dewater the WO/Sludge.
- It is **very important** that the BW can be heated to approx. **55°C**! This is to get a good result with the separation of the free oil and to achieve a good flocculation progress in the floctanks.
- In order to avoid unnecessary change of filter material it is of very big importance that the filters are **steam regenerated** approx. every 100 hrs of operation. (It's not enough only to back-flush with warm water.)

All the previous service bulletins and other important information, as e.g. updated lists of approved chemical and flocculants, can be found on our website: www.marinfloc.com.

Don't hesitate to contact us if any questions or problems!

You can easily reach us by phone: +46 (0)304-606 300, fax +46-(0)304-100 51 or via e-mail to service@marinfloc.com.

-Our mission is clear ~ a clean sea!-

2005-07-05 PL//Kada

Adress/Address:
Industrivägen 10
SE-472 95 Varekil
Sverige/Sweden

Tel: +46 (0)304 -606 300
Fax: +46 (0)304 -100 51
E-mail: marinfloc@marinfloc.com
Internet: www.marinfloc.com

Org nr/Corporate identity No:
556520-6363
Momsregnr/VAT No:
SE556520636301